Error enrolling Bioscrypt template with MV1200

Last Modified on 01/18/2022 4:05 pm EST

Symptom

Issue found on 6.4.500 Hot Fix 2.4:

While using an MVI200 (2G) enrollment reader, you receive the error:

Device does not recognize command. You may need to upgrade the firmware on this unit in order to enable this feature.

Also, OnGuard might crash when trying to store image.

Resolution

In order to resolve this issue, an older Capture U.dll from 6.4.500 TU1.1 must be registered into OnGuard:

- 1. Close out of all OnGuard programs.
- 2. Unregister the old Capture U.dll file from the OnGuard directory using the **regsvr32 /u capture U.dll** command.
- 3. Rename the old captureu.dll to captureu.bak.
- 4. Copy the **captureu.dll** file from 6.4.500 TU1.1 into the OnGuard directory (this can be obtained from release archives).
- 5. Register that .dll from the OnGuard directory using the **regsvr32 captureu.dll** command.

You can now enroll without issues.

Applies To

OnGuard 6.4.500 HF 2.4

Additional Information

This issue will be resolved per DevTrack OG-23813.