

Missing disable web Server checkmark on LNL-2220 Configuration webpage.

Last Modified on 01/10/2022 4:11 pm EST

Symptom

"Disable Web Server" checkmark is missing on the LNL-2220 Configuration Web Page.

Resolution

In order to access the Configuration Web Page, DIP Switch 1 on the LNL-2220 must be in the ON position. If DIP Switch 1 is in the OFF position, the web server section of the Configuration Web Page is unavailable.

Applies To

OnGuard (All versions)

Additional Information
