LnI-4420 Panel Randomly Reboots

Last Modified on 01/11/2022 1:59 pm EST

Symptom

LNL-4420 panels randomly reboot. Information may be lost such as masking or door schedules after the reboot.

Resolution

Apply firmware version 1.256 available for download by contacting support

Applies To

LNL-4420 panels with firmware prior to 1.256

Additional Information

None