Nisca Printers PR5300, PR5310, 5350 using YMCFK ribbon require firmware 4.3 or later

Product Name

Nisca Printers PR5300, PR5310, 5350 using YMCFK ribbon

General Information

Nisca Printers PR5300, PR5310, 5350 using YMCFK ribbon require firmware 4.3 or later.

Printers without the correct firmware will not provide the option to choose the YMCFK ribbon, and will generate an "incorrect ribbon" error.

The correct firmware and firmware update utility are available on Nisca's web site.

Applies To

OnGuard (All versions)

Additional Information