Bosch GV2 and GV3 panels are slow to report alarms

Last Modified on 04/01/2025 3:10 pm EDT

Symptom

Alarm events from Bosch GV2 and GV3 panels are delayed coming into OnGuard.

Resolution

There is a new setting in the Bosch GV2 and GV3 point index for "Alarm Abort". This must be set to "NO" for OnGuard to receive the alarms without any delay.

Applies To

Third Party Hardware

Additional Information