Delays occur when using global APB on an LNL-500, -1000, or -2000 panel with a Lantronix device.

Last Modified on 05/30/2025 4:44 pm EDT

Symptom

Delays may occur when using Global Anti-Passback on an LNL- 500, -1000, or -2000 panel with a Lantronix device.

Resolution

Use the following ACS.INI setting to adjust the poll delay setting that is likely causing the delays in the Global APB processing.

Make this change under the [Service] section of the ACS.INI file.

```
ScpLanPollDelay=200
```

 Note: This value is in milliseconds. The value of 200 is not fixed value and can be adjusted. The current default value is 1500.

Applies To

OnGuard (All versions)

Additional Information