

How to upgrade an SSL certificate for an ILS Wireless Gateway

Last Modified on 05/08/2025 6:16 pm EDT

How to upgrade an SSL certificate for an ILS Wireless Gateway

Procedure Steps

Expired or compromised SSL certificates can be upgraded using the steps below:

1. Launch a Command Prompt on the computer where the new SSL certificate files are located.
2. In the Command Prompt, change the current directory to the directory that contains the new SSL certificate files.
3. Open an FTP connection to the Wireless Gateway using the following command. Substitute the correct IP address of the Wireless Gateway for the IP address in the following command:
`ftp 192.168.165.100`
The default username is `root`.
The default password is `Netsilicon`.
4. Once logged in, verify the files currently loaded on the Wireless Gateway using the following command:
`dir`
5. Type the commands below to upload the new SSL certificate files to the Wireless Gateway:
`put WAPClient.pem`
`put svrcert.pem`
6. Log out of the FTP session using the following command:
`quit`
7. Cycle power to the Wireless Gateway to reboot it.
8. Repeat steps 1 through 7 for each Wireless Gateway in the system.
9. On the computer where Communication Server is running, in the **%ProgramFiles%\OnGuard\Certificates** folder, replace the existing version of **WAPClient.pem** with the new version of **WAPClient.pem**.
10. Restart the **LS Communication Server** service.
11. Ensure that all Wireless Gateways appear online in Alarm Monitoring.

Applies To

Lenel ILS

Additional Information

Note: SSL certificates only affect communication between Wireless Gateways and OnGuard, so the locks themselves will continue to grant or deny access properly, even if the SSL certificates expire.

Symptoms requiring new SSL certificates include errors in the LenelError.log, similar to the one below. Contact Lenel Technical Support to request new SSL certificates if you encounter the error below:

"TIME: [12/22/2010 12:33:01 PM]

SEVERITY: Warning

ERROR CODE: 0x10010008

PROGRAM: Lnlcomsrvr

FILE: .\Transport.cpp (LINE 452)

DETAILS: General warning.: OpenSSL 'SSL_connect' method failed. The return value: -1, the error code: 1. Error queue:

error:14090086:SSL routines:SSL3_GET_SERVER_CERTIFICATE:certificate verify failed"
