

LDVR Display Screen bad Image

Last Modified on 12/08/2021 7:51 pm EST

Symptom

LDVR has a horizontal split screen with video blanking in the middle of the screen.

Resolution

LDVR had an incorrect format entered in the firmware load. There are two formats to chose for the display type: NTSC or PAL. If a camera is configured in System Administration as a different type than was selected in the firmware installation, the screen will show this type of distortion.

Applies To

LDVR 7.21

OnGuard (All versions)

Additional Information
