

NGP User tab is Missing

Last Modified on 12/22/2021 10:10 am EST

Symptom

When I view Cardholders, the NGP Users tab is missing.

Resolution

An NGP intrusion panel must be added to the system. NGP controllers with access control features only will not cause that tab to be displayed since there is no intrusion functionality.

Applies To

NGP Hardware

Additional Information

None
