

How to run the recovery media on a Lenel Recorder

Last Modified on 01/10/2022 3:23 pm EST

How to run the recovery media on a Lenel Recorder

Procedure Steps

Running Recovery Disk · Power system on. · Press F2 during boot. Advanced Drive Configuration Configure SATA as - IDE · Press ESC, highlight Yes then press ENTER to save and exit BIOS · Boot from recovery disk · After recovery has completed , reboot system and enter BIOS · Press F2 during boot. Advanced Drive Configuration Configure SATA as - AHCI · Press ESC, highlight Yes then press ENTER to save and exit BIOS

Applies To

OnGuard (All versions); Windows Server 2008; Windows Server 2008 R2; Windows Vista; Windows XP; Windows 7

Additional Information
