

Inputs triggered on the LNL-1340-M2K are not seen in OnGuard

Last Modified on 01/11/2022 11:35 am EST

Symptom

Inputs triggered on LNL-1340-M2K are not seen in OnGuard.

Resolution

Check the firmware revision of the LNL-1340-M2K. In Alarm Monitoring, select **Options > Display Device Firmware Revisions**. If Alarm Monitoring indicates the device does not have the current firmware revision, right-click the LNL-1340-M2K and download the firmware. When the LNL-1340-M2K comes back online with current firmware, test the inputs again.

Note: The Lenel Access Control Hardware Compatibility Chart also identifies the supported firmware revisions for each compatible version of OnGuard.

Applies To

Lnl-1340-M2K
OnGuard 7.2 or Newer

Additional Information

None
