

M Series LNL-1100-20DI Firmware

Last Modified on 06/02/2025 4:44 pm EDT

Product Name

M Series LNL-1100-20DI

General Information

Upgrading the M Series LNL-1100-20DI from firmware version 1.32.1 or earlier will render the access panel unusable. The LNL-1100-20DI has two (2) on-board processors, one for every ten DIs. Upgrading the firmware for the first processor will succeed, but attempting to upgrade the second will result in corrupting the board, rendering it unusable. Only upgrade LNL-1100-20DI boards with firmware version 1.32.2 or later.

Applies To

M Series LNL-1100-20DI with firmware version prior to 1.32.1

Additional Information

If the client is in possession of LNL-1100-20DI with firmware version of 1.32.1, then contact RMA@lenel.com for an advanced exchange.
