

# Why the playback window time line displays 0.0 fps?

Last Modified on 05/23/2025 2:03 pm EDT

## Question

Why does the playback window time line display 0.0 fps?

## Answer

When viewing recorded video playback in Alarm Monitoring, the frame rate indicated on the playback window time line displays as **0.0 fps** if the video was recorded in time lapse mode.

This is a product limitation.

## Applies To

OnGuard (All versions)

## Additional Information

---