# Capicom.dll may be flagged as a vulnerability

Last Modified on 05/30/2025 11:44 am EDT

### General Information

Lenel Network Video Recorder

#### Resolution

Capicom.dll, may be flagged as a vulnerability on a system security scan. This is a .dll that is only used by LnrCfgSvc.exe and is no longer used by LNVR and can be safely removed.

## Applies To

LNVR versions 7.7 and below.

#### Additional Information

The vulnerability flagged is only possible if an attacker hosts a website with a page used to exploit the vulnerability. Since LNVRs do not typically use the machine's web browser this exploit is considered high but not critical.

© 2024 Honeywell International Inc. All Rights Reserved.