

FIPS 201 with PACS Server 5.22 and later

Last Modified on 04/08/2025 12:43 pm EDT

Symptom

Unable to connect to FIPS 201 and getting the error "The client and server cannot communicate because they do not pose a common algorithm."

Resolution

The newest PACS service uses TLS encryption now, with the following prerequisites:

- The certificate must be installed in Third-Party Root Certification Authorities.
 - When this is installed, it will also install the certificate in the Trusted Root Certification Authorities. This is not a problem as long as the certificate is not duplicated in either location.
 - This needs to be done on the server and clients enrolling from PACS.
- TLS 1.0 and 1.1 must be enabled on the server and clients enrolling from PACS.

Applies To

PACS Server 5.22 and later

Additional Information

© 2024 Honeywell International Inc. All Rights Reserved.
